



## ED-T43L-V updates and changes

In this document you will find what is changed and what has been updated between the different releases of ED-T43L-V since revision 1.0-1-00.

### 1.0-1-04

- Fix of a bug in the timer channel. Timer channel normal showed wrong information in period 2 and period 3 on Wednesday.

### 1.0-1-03

- Added a new setting in the Account-Settings to be able to disable the Standby-mode.
- Fix of a bug in the graphical overview of the timer channels.
- Some parameters in the account settings were not permanently stored in the non-volatile memory. This is now fixed.

### 1.0-1-02

- Wrong scaling of flow values is fixed
- Efficiency exchanger calculation is now visible
- Implementation of Mode-switch to the home-screen
- Extra time channel 4 is now visible when an extra fan is activated
- Bug in the display of alarm texts is fixed

### 1.0-1-01

- Support of additional languages, Swedish, German, French and Dutch
- Small minor improvements

**AB Regin**  
**Head office Sweden**

Tel: +46 (0)31- 720 02 00  
E-mail: [info@regin.se](mailto:info@regin.se)  
[www.regincontrols.com](http://www.regincontrols.com)

Box 116  
428 22 Kållerød

**Visiting address:**  
Bangårdsvägen 35  
428 36 Kållerød

  
THE CHALLENGER